
## Jones House Brick Wall Repair



- -April high wind blew ½ of big tree into rear brick wall
- -"Blew out" 12 foot wide section of brick wall















Done except for putting 180 Lb. Capstones back in place













How to remove "Excess" mortar from bricks




## Repairs Completed



## Strevell House











Back steps on East Side







Before After









Front Finished ©











South Side Repair Complete North Side Repaired Also

## The End